



Hanrun paper

HANRUN PAPER INDUSTRIAL CO., LIMITED

Process of Heat Transfer PU Vinyl:

No need print, just a cutting plotter and a heat press machine

1. Cutting:


- Equipment: Cutting plotter
- Cutting setup set up: Load the image into the plotter software; Change the image into mirror version; Click the track window, choose the cutting area; Follow the image outer edge cutting.
Speed suggest: 6; Thickness suggest:5

2. Transferring:

- Time: 20seconds
- Temperature:165 °C
- Pressure: moderate pressure

Introduction usage

1. Cutting:



A: Load the image into plotter software. Make it in Mirror type.



B: plotter working

2. Peel off the base paper:



C: Peel off the base paper slowly.



D: Outcome after peel off



3. Transferring & Cold peel:



F: Heat press.
Temperature 165centigrade;
Transfer time: 20seconds



E: Cold peel.



G: Cold Peel. Peel slowly.



H: The result, bright



CONTACT

Address: 2#102, United Cube,155Longpan Road, Xuanwu District, Nanjing-city, China

Phone: 86-025-83377515

Email: admin@hrpaper.cn

Web: www.hrpaper.cn

www.hanrunpaper.com